

Unused Detank DE220BLC 323 DL

General characteristics

Brand	Unused Detank
Subcategory	Crawler excavator
Year of construction	2015
Colour	Otherwise
Condition	Used



Technical specifications

Drive	tracking
Assets	116kw

Description

Unused Detank DE220BLC with: Rear view camera Cummings QSB6.7 engine Airconditioning Verachttert quick coupler Roof protection Front screen guard now owned by zoomlion